



## Parts needed to mount the DP-45-MOC-ZO fastener





## **Tools needed for mounting:**

- Allen wrench
- drill

**NOTE!** A list of products corresponding with the selected accessories is available at www.klusdesign.eu/uk.

www.klusdesign.eu 1






1. Drill a hole with a diameter of 5 mm in the selected extrusion.




**2.** Remove the insulation on the section inserted inside the screw and the head. Run the cable (A) through the holes in the mounting bracket (B) and in the head (C). Connect power to the LED strip. Attach the lighting fixture to the mounting bracket.



**3.** Insert the rod into the mounting bracket of the head (C). Block it by tightening it with the Allen wrench.



**4.** Suspend the lighting fixture using a selected suspension and power supply system.



www.klusdesign.eu 2