


Parts needed to mount the INTER extrusion



Tools needed for mounting:


- drill

- screwdriver
- screws
- hand saw
- Allen wrenches (dia. 3 mm, dia. 5 mm)

NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure. More mounting procedures and related accessories can be found at klusdesign.eu






Inspiring Solutions

KLUŚ







top view


Κ G Н G G 0 Κ K G Κ В A

8. Insert the extrusion (B) into the mounting strip (A) and connect power.









them with the Allen wrench. cross - section

KLUŚ_® Inspiring Solutions