


Instruction includes methods of montage:



Tools needed for mounting:

- drill
- pliers
- allen wrench
- soldering iron

NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure.


More mounting procedures and related accessories can be found at klusdesign.eu



JAZ - suspended fixture mounting instructions 2. Rod - conductive driven power supply

*If fully built fixtures are ordered and received from KLUS please skip to #3


1. Drill the holes in the JAZ extrusion to mount the PUSZ-PRET-ZM fasteners.



top view




3. Connect the wires to the Install the power connectors of the PUSZ-PRET-ZM fasteners and install the whole fasteners with rods on the JAZ extrusion. The fastener installation manual can be downloaded at www.klusdesign.eu.




5. Install the W-KG-Z ceiling fasteners. The fastener installation manual can be downloaded at www.klusdesign.eu. Connect the cables, each for the single power pole to the fasteners. The cables should go through a pre-drilled hole just under the masking cover of the fastener.







Negative pole has to be soldered

4. Install the cover and both end caps.



6. Mount the fixture with rods into the ceiling fasteners. Mind that the power poles connected to the rods should match the ones connected to the fasteners.








JAZ - suspended fixture mounting instructions 1. Rod - non-conductive (requires drop lead)


*If fully built fixtures are ordered and received from KLUS please skip to #3





JAZ - suspended fixture mounting instructions 3. Wire - non-conductive (requires drop lead)

*If fully built fixtures are ordered and received from KLUS please skip to #3






JAZ - suspended fixture mounting instructions 4. Wire - conductive driven power supply

*If fully built fixtures are ordered and received from KLUS please skip to #3


1. Drill the holes in the JAZ extrusion to mount the PUSZ-LIN-ZM fasteners.



top view




3. Connect the wires to the Install the power connectors of the PUSZ-LIN-ZM fasteners and install the whole fasteners with steel wires on the JAZ extrusion. The fastener installation manual can be downloaded at www.klusdesign.eu.




5. Install the W-KG-Z ceiling fasteners. The fastener installation manual can be downloaded at www.klusdesign.eu. Connect the cables, each for the single power pole to the fasteners. The cables should go through a pre-drilled hole just under the masking cover of the fastener.






4. Install the cover and both end caps.



6. Mount the fixture with steel wires into the ceiling fasteners. Mind that the power poles connected to the steel wires should match the ones connected to the fasteners.



cross-section side view